

P.O. Box 1285 Ann Arbor, MI 48106

www.thetford.com

# Service Bulletin

Notice of Replacement Part 42036, 42037 Seat & Cover Kit

#### Date:

Between 05.01.12 and 08.08.12 improper assembly of Seat and Cover Kit 42036, 42037, 42178, 42179 occurred.



**Warning!** Problem can result in pins falling out and hinge becoming unattached to the seat and/ or cover causing personal injury.

#### **Models Affected:**

Aqua-Magic® Style II, Residence

### **Action Step:**

Replace the seat and cover assembly under a warranty claim using the warranty replacement part numbers listed below. **Problem should NOT be repaired-replace the part!** Order appropriate kit specified below.

# Warranty Replacement Part Numbers:

- 42037 Bone
- 42036 White

## Pin / Hinge Examples



